



HEAVYWEIGHT CRYSTAL
SYTRENE PLASTIC PINT TUMBLER.
HOUSEHOLD DISHWASHER SAFE.



PT317



1 Piece
OPF6 *



1 Piece
OPWS9 *



1 Piece
H15 *

ST7258
OPTIONAL
SHAKER TOP



PRICING
\$1.48 EACH (T)

ADDITIONAL CHARGES AND INFORMATION

STANDARD LEAD-TIME	6 business days after proof approval (up-to 5M)
PRINT REGISTRATION	Allow up-to 1/16" maximum movement between colors
RUSH SERVICE	Call to check availability
"DOUBLE RUSH"	\$40.00(V) per order (4-5 business days after proof approval)
"TRIPLE RUSH"	\$55.00(V) per order (2-3 business days after proof approval)
PRESS STOPS	\$25.00(V) per press stop (to change ink color or design)
SET-UP CHARGE	\$25.00(V) PER COLOR
PMS COLOR INK MIX CHARGE	\$20.00(V) PER ORDER
METALLIC INK UP-CHARGE	\$15.00(V) PER ORDER
PROOFS:	No charge for the first + one revision.
(Fax or electronic)	(48 hour lead time)
PRODUCTION PROOFS	\$25.00(V) per color + set-up charge (5 business day lead-time)

Item#	Case Wgt	Case/ Pkg	Case Dim. Length x Width x Depth	Imprint Area Width x Height x bw	Max. Colors
OPF6	6lbs.	48/ Case	15"x11"x10"	1 1/2"x2 1/4"x1 1/2"	2
OPWS9	7lbs.	36/ Case	18"x12"x10"	1 3/4"x1"x1 3/4"	2
H15	10lbs	24/ Case	18"x14"x19"	2"x1 1/2"x2"	2
PT317	10lbs	48/ 1	20"x14"x10"	2 1/2"x2 1/2"x2"	4

Price Per Piece - Includes 1-Color Print (7R)

Item#	Item Description	50	100	250	500	1M	2.5M	5M
OPF6	6 oz. Clear Champagne Flute	\$2.69	\$2.56	\$2.24	\$2.13	\$2.06	\$1.97	\$1.93
OPWS9	9 oz. Clear Wine Goblet	\$3.24	\$3.08	\$2.75	\$2.69	\$2.63	\$2.56	\$2.50
H15	15 oz. Hurricane Glass	\$4.40	\$4.27	\$3.96	\$3.86	\$3.80	\$3.77	\$3.75
PT317	15oz. Heavyweight Plastic Pint	\$2.56	\$2.44	\$2.13	\$2.03	\$1.96	\$1.91	\$1.79
	Add for each add'l ink color	\$.62	\$.50	\$.35	\$.30	\$.25	\$.23	\$.20
	Add for identical second side prints (No second side charge for 1-color print)	\$.43	\$.27	\$.19	\$.17	\$.14	\$.13	\$.11

* Crystal styrene plastic, reusable & dishwasher safe (non-commercial)

Production Note:

While every effort is made to maintain quality, the nature of plastic cups is such that they may exhibit scratches from packaging or shipping. This is normal and NOT a defect.